

m/04910647  
Lynn  
Shaw Environmental, Inc. 0001



7604 Technology Way  
Denver, CO 80237  
720.554.8202  
Fax 720.554.8298

January 13, 2009

Department of Natural Resources  
Division of Oil, Gas and Mining  
Attn: Mining Regulatory Program  
1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801

Re: 2008 Annual Progress Report

Mining Regulatory Program:

In accordance with OGM requirements please find a completed Large Mining Operation 2008 Progress Report.

Please feel free to contact me should you have any questions. I can be reached at (720)554.8202 or (435)433.8000.

Sincerely,

A handwritten signature in black ink, appearing to read "Gary D. Parks", followed by a stylized flourish.

Gary D. Parks P.G.  
Project Manager

cc: file

RECEIVED

JAN 20 2009

DIV. OF OIL, GAS & MINING

0001

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

LARGE MINING OPERATIONS 2008 PROGRESS REPORT  
January 1, 2008 to December 31, 2008

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

1. Mine Permit Number: M/049/047
2. Mine Name: Lime Peak Quarry
3. Name of Operator/Permittee: Shaw Environmental, Inc.

Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention.

4. Mine Location: Utah County, Utah
5. Report the gross amount of ore mined and waste moved, and the disposition of the materials (onsite stockpiles, sold, waste pile, regraded, etc.):

Gross Ore Mined \_\_\_\_\_ Tons, or 0 yd<sup>3</sup>  
Waste Material Moved \_\_\_\_\_ Tons, or 0 yd<sup>3</sup>  
New Disturbance 0 Acres during 2008  
Area Reclaimed 0 Acres during 2008  
Total Disturbed Area 23 Acres\*

\*Total mine disturbance from the beginning of mining operations through the end of 2008.

Was the ore shipped off site? If not, where is the ore located? Processed rock products are used for remediation at the Eureka Mills Superfund Site.  
Where is the waste located? Unusable rock is stored at the quarry as described in the Permit.

6. Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE for an application for full or partial bond/site release).  
None. All of the distrubed area is still being used.
7. Include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.

I hereby certify, under penalties of law, the information provided in this report is true and correct to the best of my knowledge and belief.

Name (Typed or Print): Gary D. Parks  
Title of Operator: Project Manager  
Signature of Operator: Gary D. Parks  
Date: 1/13/09



